

# NuKut SS 303 Concentration Control by Refractometer

Note: pH should be kept from 8.0 to 9.8

Concentration is best from 5 to 10% = Refrac reading 3.5 to 5.5

